

# v52-Series Communication protocol

## Read Example (Full Measurement)

Byte#	0		1					
Send By Master	0x50		0xAA		0x51			
	S	101000	0	A	10101010	A	P	S
	Adress(0x28)		W	Command				Adress(0x28)

Byte#	0	1	2	3	4	5	6	
Receive from Slave	A	[15:8]	A	[7:0]	A		A	[15:8]
	Status	Pressure Data		xx	Temperature Data		xx	A

## Pressure conversion:

	Raw Readout (Byte 2&3)
At 0 Pressure	6553
At FS Pressure	58982

Formula:  $(\text{RawData} - 6553) / (58982 - 6553) * \text{FS Pressure}$

Example with 52DL-007P at 7 Psi:  $(58982 - 6553) / (52429) * 7 = 7\text{Psi}$

## Temperature conversion:

$\text{TempData} / 65535 * 125 - 40 = ^\circ\text{C}$

## Status Byte:

Standard status byte: 0x40 (0x68 also acceptable). In case of other status byte please contact support.

Bit#	7	6	5	4	3	2	1	0
Meaning	0	Power	Busy	Mode		Memory Error	Connection Error	Math Saturation

**Example code:**

```

#include <Wire.h> // i2c library
#include <stdio.h>

byte Address = 0x28; //52-Series adress found on Datasheet or I2C Scanner

void setup() {
  Serial.begin(9600);
  Wire.begin(); //start communication for i2c
}

void loop() {
  Wire.beginTransmission(Address);
  Wire.write(0xAA);
  Wire.endTransmission();
  Wire.requestFrom(Address, 6); // requesting to read all 6 bytes from the Sensor adress
  //put the output in variable c
  byte c1 = Wire.read(); //read 6 bytes and define variable for them
  byte c2 = Wire.read();
  byte c3 = Wire.read();
  byte c4 = Wire.read();
  byte c5 = Wire.read();
  byte c6 = Wire.read();

  unsigned short c = (c2 << 8) + c3; //Byte 2 & 3 for Pressure output
  unsigned short d = (c5 << 8) + c6; //Byte 5 & 6 for Temperature output
  float p, t; //p = Pressure output, t = Temperature output

  p = (float)(c - 6553) / 52429 * 482.63301051; // 7psi = 482.63301051mBar: insert Range of your
  Version there

  t = (float)d / 65535 * 125 - 40; //Formula for Temp. calculation: 16-bit temperature output / 65535
  * 125 - 40 = temperature(degC)

  Serial.print("Pressure(mBar):");
  Serial.print(p);
  Serial.print('\n');
  Serial.print("Temperature(°C):");
  Serial.print(t);
  Serial.print('\n');
  Serial.print("Status: 0x");
  Serial.print(c1, HEX); //c1 is Status Byte
  Serial.print('\n');
  Serial.print('\n');
  delay(500);
}

```

## We are here for you. Addresses and Contacts.

---

### Headquarter Switzerland:

Angst+Pfister Sensors and Power AG  
Thurgauerstrasse 66  
CH-8050 Zurich  
Phone +41 44 877 35 00  
[sensorsandpower@angst-pfister.com](mailto:sensorsandpower@angst-pfister.com)

### Office Germany:

Angst+Pfister Sensors and Power Deutschland GmbH  
Edisonstraße 16  
D-85716 Unterschleißheim  
Phone +49 89 374 288 87 00  
[sensorsandpower.de@angst-pfister.com](mailto:sensorsandpower.de@angst-pfister.com)

---

Scan here and get an overview of personal contacts!



[sensorsandpower.angst-pfister.com](https://sensorsandpower.angst-pfister.com)

---