




		Messbereich	Druckart	Ausgangstyp	Versorgungsspannung [V]	Temp. Bereich [°C]	Temperaturkompensation	Montageart	Druckanschluss
	ME501-Series	0 ... 50 bar	Absolute, Gauge, Sealed gauge	Differential mV/V		-40 ? +135°C (-40°F ? +275°F)	Available		Unported
	ME600-Series	0 ? 600 bar	Gauge	Differential mV/V		-40 ? +135°C (-40°F ? +275°F)	Available		Unported
	ME782-Series	0 ? 600 bar	Absolute, Gauge, Sealed gauge	Ratiometric 0.5V ? 4.5V, I2C		-25 ? +125°C (-13°F ? +257°F)	Available		Unported
	ME790-Series	0 ? 400 bar	Gauge	Ratiometric 0.5V ? 4.5V		-25 ? +125°C (-13°F ? +257°F)	Available		Unported
	ME900-Series	0 ? 100 bar	Gauge	Ratiometric 0.5V ? 4.5V		-20 ... +85 (-4 °F ... +185 °F)	Available		Unported
	PEWA141	0 to 70 mbar...1000 bar	Gauge, Absolute, Sealed gauge	Analog	3.3...5...24		Yes	Connector	Unported
	PEWA2701	0 to 70 mbar...1000 bar	Gauge, Absolute, Sealed gauge	Digital	3.3...5	-20 to +80	Yes	Connector	Unported
	89-800A	0 to 10...80 bar	Gauge	Unamplified	0...10	-40 to +125	Yes	Connector	Axial port

		Messbereich	Druckart	Ausgangstyp	Versorgungsspannung [V]	Temp. Bereich [°C]	Temperaturkompensation	Montageart	Druckanschluss
	PEWA700	0 to 10 mbar...600 bar	Gauge, Vacuum, Absolute, Sealed gauge	Analogue, Digital	4.5...5.5	-40 to +125	Yes	Solder pad	Axial port
	PSPA372	0 to 100 mbar...40 bar	Gauge	Analogue	4.5...5.5	-40 to +125	Yes	Solder pad	Axial port
	PSD18-210-O	0 to 0.02...7 bar	Gauge, Vacuum, Absolute	Unamplified	0...10	-40 to +125	No	Solder pad	Axial port, unported
	PSD18-210-P	0 to 0.02...7 bar	Gauge, Vacuum, Absolute	Unamplified	0...10	-40 to +125	Yes	Solder pad	Axial port, unported
	PSD18-210-T	0 to 0.02...7 bar	Gauge, Vacuum, Absolute	Analogue	2.7...5.5	-40 to +125	Yes	Connector	Axial port, unported
	PSD18-410-O	0 to 0.1...7 bar	Gauge, vacuum, absolute	Unamplified	0...10	-40 to +125	No	Connector	Axial port, unported
	PSD18-410-P	0 to 0.1...7 bar	Gauge, Vacuum, Absolute	Unamplified	0...10	-40 to +125	Yes	Connector	Axial port, unported
	PSD18-410-T	0 to 0.1...7 bar	Gauge, Vacuum, Absolute	Analogue	2.7...5.5	-40 to +125	Yes	Connector	Axial port, unported

		Messbereich	Druckart	Ausgangstyp	Versorgungsspannung [V]	Temp. Bereich [°C]	Temperaturkompensation	Montageart	Druckanschluss
	PSD18-411-O	0 to 0.35...35 bar	Gauge, Vacuum, Absolute	Unamplified	0...10	-40 to +125	Yes	Connector	Axial port, unported
	PSD18-411-P	0 to 0.35...35 bar	Gauge, Vacuum, Absolute	Unamplified	0...10	-40 to +125	Yes	Connector	Axial port, unported
	PSD18-411-T	0 to 0.35...35 bar	Gauge, Vacuum, Absolute	Analogue	2.7...5.5	-40 to +125	Yes	Connector	Axial port, unported
	PKD15-516	0 to 1...20 bar	Gauge, Absolute	Unamplified	0...30	-40 to +135	No	THT, solder pad	Axial port, unported
	PKD18-511	0 to 0.5...600 bar	Gauge, Absolute	Unamplified, Analogue	0...30	-40 to +135	No	THT, solder pad	Axial port, unported
	PKD18-611	0 to 2...400 bar	Gauge, Absolute	Unamplified, Analogue	0...30	-40 to +135	No	THT, solder pad	Axial port, unported
	KKD18-720-V	0 to 0.1...50 bar	Gauge, Vacuum, Absolute	Analogue, Digital	2.7...5.5	-40 to +125	Yes	Connector	Axial port, unported
	KKD34-705-V	0 to 0.012...20 bar	Gauge, Absolute	Analogue, Digital	2.7...5.5	-40 to +125	Yes	Connector	Axial port, unported

We are here for you. Addresses and Contacts.

Headquarter Switzerland:

Angst+Pfister Sensors and Power AG
Thurgauerstrasse 66
CH-8050 Zurich
Phone +41 44 877 35 00
sensorsandpower@angst-pfister.com

Office Germany:

Angst+Pfister Sensors and Power Deutschland GmbH
Edisonstraße 16
D-85716 Unterschleißheim
Phone +49 89 374 288 87 00
sensorsandpower.de@angst-pfister.com

Scan here and get an overview of personal contacts!



sensorsandpower.angst-pfister.com