


		Design	Measuring range [± g]	Bandwidth [Hz]	DC / AC response	Amplified	Axis	Output	Sensitivity
	SCA3300-D01	IC	1,5 to 6,0	0 to 88	DC	Yes	4	SPI	5400 LSB/g
	SCA3300-D01-PCB	Platine	1,5 to 6,0	0 to 88	DC	Yes	4	SPI	1250 to 5400 LSB/g
	SCA3100-D04	IC	1,5 to 6,0	0 to 55	DC	Yes	3	SPI	typ. 900 Counts/g
	SCA3100-D07	IC	6	0 to 55	DC	Yes	3	SPI	typ. 650 Counts/g
	SCA3100-D04 PWB	Platine	2	0 to 55	DC	Yes	4	SPI	typ. 900 Counts/g
	SCA3100-D04 DemoKit	Evalboard	2	0 to 55	DC	Yes	3	USB	typ. 900 Counts/g
	SCA1000-D01	IC	1.7	0 to 80	DC	Yes	2	Voltage, SPI	1,2 V/g
	CAS21 Gemini	IC	0.85 to 96	0 to 250	DC	Yes	2	Voltage, SPI	10 to 1150 mV/g, 320 to 33500 lsb/g

	Design	Measuring range [±g]	Bandwith [Hz]	DC / AC response	Amplified	Axis	Output	Sensitivity	
	CAS29 Gemini	IC	0.85 to 96	0 to 250	DC	Yes	2	Voltage, SPI	10 to 1150 mV/g, 320 to 33500 lsb/g
	CAS21 Gemini Evalboard	Evalboard	0.85 to 96	0 to 250	DC	Yes	2	Voltage, SPI	10 to 1150 mV/g, 320 to 33500 lsb/g
	CAS29 Gemini Evalboard	Evalboard	0.85 to 96	0 to 250	DC	Yes	2	Voltage, SPI	10 to 1150 mV/g, 320 to 33500 lsb/g

We are here for you. Addresses and Contacts.

Headquarter Switzerland:

Angst+Pfister Sensors and Power AG
Thurgauerstrasse 66
CH-8050 Zurich
Phone +41 44 877 35 00
sensorsandpower@angst-pfister.com

Office Germany:

Angst+Pfister Sensors and Power Deutschland GmbH
Edisonstraße 16
D-85716 Unterschleißheim
Phone +49 89 374 288 87 00
sensorsandpower.de@angst-pfister.com

Scan here and get an overview of personal contacts!



sensorsandpower.angst-pfister.com